



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3914-041
Job Sheet 202635



Part No: D3914-041

Job Qty: 1 pcs

Part Name: Long Basket Lid Assembly (350)



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 10/31/19

Job Tracking No:

Due Date: 12/10/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG D4020 REV A SHEET 2, D3914 REV D SHEETS 1,2,3 IPP Rev:A new issue DD 10.03.19 verified by:EC
IPP Rev:B as per dwg revB DD 10.08.18 verified by:EC IPP Rev:C 13.03.14 AS PER DWG REV.pc1 DD
VERF:JLM IPP REV:D 13.06.21 DWG REV.C DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Large Fab - Basket - 1	1 pcs	12/10/19		0.00	10.00	Large Fab - 1		<i>MFL</i>
							Large Fab - 10		
							Large Fab - 2		
							Large Fab - 3		
							Large Fab - 4		
							Large Fab - 5		
							Large Fab - 6		
							Large Fab - 7		
							Large Fab - 8		
							Large Fab - 9		
							Large Fab - 11 (Various)		
							Large Fab - 12		
110	QC 9	1 pcs	12/10/19		0.00	0.00	QC 9 - 10		
							QC 9 - 18		
							QC 9 - 24	DAS	
							QC 9 - 43	24	
							QC 9 - 50	9-89	
							QC 9 - 9		
120	QC 5	1	12/10/19		0.00	0.00	QC 5 - 10		
							QC 5 - 12		
							QC 5 - 17		
							QC 5 - 18		
							QC 5 - 19		
							QC 5 - 22	DAS	
							QC 5 - 24	24	
							QC 5 - 3	9-89	
							QC 5 - 43		
							QC 5 - 49		
							QC 5 - 51		



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S237152



Part: D3914-041

Job No: 202635

Serial No/Batch: S237152

Revision: A/D

Inspector:

Exp Date:

Instructions: Various STC's

Date: 12/04/19

Plex 10/31/19 12:53 PM Dart.lajeunesse.marie

					QC 5 - 58	
					QC 5 - 68	
					QC 5 - 9	
					QC 5 - 50	
					QC 5 - 30	
					QC 5 - 40	
					QC 5 - 61	
					QC 5 - 81	
130 Powdercoat - 4 Black Sand -	1	12/10/19	0.00	0.40	Powdercoat - 1 - B4B	
B4B M156 440.	pcs				Powdercoat - 2 - B4B	
START: 1:00					Powdercoat - 3 - B4B	BL 19-12-9
END: 1:30					Powdercoat - 4 - B4B	
135 QC 3	1	12/10/19	0.00	0.00	QC 3 - 10	
	pcs				QC 3 - 13	
					QC 3 - 15	AL 19-12-9
					QC 3 - 17	
					QC 3 - 18	
					QC 3 - 2	
					QC 3 - 28	
					QC 3 - 3	
					QC 3 - 30	
					QC 3 - 34	
					QC 3 - 36	
					QC 3 - 41	
					QC 3 - 51	
					QC 3 - 58	
					QC 3 - 59	
					QC 3 - 68	
					QC 3 - 9	
					QC 3 - 40	
					QC 3 - 19	
					QC 3 - 43	
					QC 3 - 24	
					QC 3 - 61	
					QC 3 - 81	
140 Handfinish - 3-1- WingWalk-	1	12/10/19	0.00	0.80	Handfinish - 3 - 1 -	
B4B	pcs				B4B	AL 19-12-9
					Handfinish - 3 - 2 -	
					B4B	
					Handfinish - 3 - 3 -	
					B4B	
					Handfinish - 3 - 4 -	
					B4B	
					Handfinish - 3 - 5 -	
					B4B	
150 QC 3	1	12/10/19	0.00	0.00	QC 3 - 10	
	pcs				QC 3 - 13	
					QC 3 - 15	
					QC 3 - 17	
					QC 3 - 18	
					QC 3 - 2	
					QC 3 - 28	
					QC 3 - 3	
					QC 3 - 30	
					QC 3 - 34	
					QC 3 - 36	
					QC 3 - 41	
					QC 3 - 51	
					QC 3 - 58	
					QC 3 - 59	BE 19-12-10

DAS
15
9-89DAS
59
9-89

[illegible]

				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
170 QC 21 - SA	1	12/10/19	0.00 0.00	QC 21 - SA - 21	DAS 21
	pcs			QC 21 - SA - 70	3.00
				QC 21 - SA - 53	DEC 10 2019

Part Op 100 - (Weld per dwg A/R S.S. rod Batch: 139013 - 1- assemble ribs , weld as per dwg D3914 using DT9607A 2- weld Descriptions: hinge (3) and Mounting brackets as per dwg D3914 ***Cut out mesh where label plate goes in center off basket lid as per dwg D4020-5. Make sure to place mesh correctly on lid, check with label plate before tacking mesh***

110 - QC9- Inspect visual per QSI004- Fusion Welds

120 - QC5- Inspect part completeness to step on W/O

130 - Black Sandtex(Ref:4.3.5.7) per QSI005 4.3 *** mask sides of hinge prior to powdercoat***

135 - QC3- Inspect Part Finish

140 - Wing Walk as per dwg QSI005 4.4 Batch _____ 1- Mask data plate and apply wing walk on outside surface of mesh as per dwg 2- Install label as per dwg ***Mask label plate to size of label, use scotchbrite red pad to lightly sand area for label, apply label ***

150 - QC3- Inspect Part Finish

160 - Identify as per dwg & Stock Location: _____

170 - QC21- Final Inspection - Work Order Release

M4# 013269

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2581	Mounting Bracket	2 pcs (2 ea)	100-Large Fab - Basket - 1	5214921
D3914-1	Rib	2 pcs (2 ea)	100-Large Fab - Basket - 1	5226327
D3914-7	Rib	2 pcs (2 ea)	100-Large Fab - Basket - 1	5226322
D4016-3	Hinge Half, Lid	3 pcs (3 ea)	100-Large Fab - Basket - 1	5221960
D4018-5	Rib	9 pcs (9 ea)	100-Large Fab - Basket - 1	5210656
D4020-5	Mesh (350 Basket Long, Lid)	1 pcs (1 ea)	100-Large Fab - Basket - 1	5229696
D4021-3	Data Plate	1 pcs (1 ea)	100-Large Fab - Basket - 1	5172801
D4035-043	Lid Rib Assembly, Aft (350 Basket)	2 pcs (2 ea)	100-Large Fab - Basket - 1	5232735

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Large Fab - Basket - 1	D2581	2	81	0
	D3914-1	2	12	0
	D3914-7	2	12	0
	D4016-3	3	253	0
	D4018-5	9	86	0
	D4020-5	1	2	0
	D4021-3	1	7	0
	D4035-043	2	8	0

Part Specifications

Specifications could not be found.

Plex 10/31/19 12:53 PM Dart.lajeunesse.marie

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042)	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐ ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled		FAULT CATEGORY ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					